

# SATIR


## PK-80

### The Real Tablet Thermal Camera


Ideal Portable Thermal  
Solution in the Age of the Internet



1 Install the battery




2 Boot




Press and hold the power switch for 3s

3 Remove the lens cover




Push the lens cover counterclockwise

4 Start the thermal imager




Click the "PK" icon

### 5 Image adjustment




Click the "Shutter" icon

### 6 Freeze the image




Click the "Freeze" icon

### 7 Save the image




1. Click the "Image"  
2. Click the "Camera" icon

### 8 Turn off the thermal imager



1. Press and hold the power switch for 3s  
2. Press the "Power off"

### 9 Close the lens cap clockwise



GUANGZHOU SAT INFRARED TECHNOLOGY CO.,LTD.

Add: No. 10, DONGJIANG AVE, GETDD, GUANGZHOU, CHINA, 510730

Tel: +86 20 82229925 Fax: +86 20 82227947 Email: sat@sat.com.cn

[www.sat.com.cn](http://www.sat.com.cn)

SATIR Europe (Ireland) Company Limited

Add: Marleys Business Park, Marleys Lane, Drogheda, Co. Louth, A92 PX6P, Ireland

Tel: +353 (0)41 9844371 Email: enquiry@satir.com

[www.satir-eu.com](http://www.satir-eu.com)